

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA-2020-0968; Project Identifier MCAI-2020-00974-T; Amendment 39-21304; AD 2020-22-08]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Airbus SAS Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

---

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A320-251N and -271N airplanes; Model A321-251N, -271N, -272N, -252NX, and -271NX airplanes; Model A330-243, -343, and -941 airplanes; and Model A350-941 and -1041 airplanes. This AD was prompted by reports of removable display units (RDUs) found undocked from the hosting display docking stations (DDSs). This AD requires removal of the RDUs or implementation of an operational restriction, and a one-time inspection of the RDU installation onto the DDS and, depending on findings, accomplishment of applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD becomes effective November 19, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 19, 2020.

The FAA must receive comments on this AD by December 21, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0968.

### **Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0968; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225; email: [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

### **SUPPLEMENTARY INFORMATION:**

#### **Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0155, dated July 14, 2020 (“EASA AD 2020-0155”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A320-251N and -271N airplanes; Model A321-251N, -271N, -272N, -252NX, and -271NX airplanes; Model A330-243 airplanes; Model A330-343 airplanes; Model A330-941 airplanes; and Model A350-941 and -1041 airplanes.

This AD was prompted by reports of RDUs found undocked from the hosting DDSs caused by incorrect RDU installation or damage to the DDS. The FAA is issuing this AD to address undocked RDUs, which could lead to detachment of an RDU, possibly resulting in injury to airplane occupants. See the MCAI for additional background information.

#### **Related IBR Material Under 1 CFR Part 51**

EASA AD 2020-0155 describes procedures for removal of the RDUs or implementation of an operational restriction, and a one-time inspection of the RDU installation onto the DDS and, depending on findings, accomplishment of applicable corrective actions. Corrective actions include repair or replacement of the DDS, reinstallation or replacement of the RDU, and realignment of the RDU and DDS. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### **FAA's Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the FAA evaluated all pertinent information and

determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

### **Requirements of This AD**

This AD requires accomplishing the actions specified in EASA AD 2020-0155 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

### **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0155 is incorporated by reference in this final rule. This AD, therefore, requires compliance with EASA AD 2020-0155 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service information specified in EASA AD 2020-0155 that is required for compliance with EASA AD 2020-0155 is available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0968.

### **FAA's Justification and Determination of the Effective Date**

There are currently no domestic operators of these products. Therefore, the FAA finds that notice and opportunity for prior public comment are unnecessary and that good cause exists for making this amendment effective in less than 30 days.

### **Comments Invited**

This AD is a final rule that involves requirements affecting flight safety, and the FAA did not precede it by notice and opportunity for public comment. The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2020-0968; Project Identifier MCAI-2020-00974-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will consider all comments received by the closing date and may amend this AD based on those comments.

The FAA will post all comments the FAA receives, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the FAA receives about this AD.

### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial

information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to the person identified in the FOR FURTHER INFORMATION CONTACT section. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### **Regulatory Flexibility Act (RFA)**

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

### **Costs of Compliance**

Currently, there are no affected U.S.-registered airplanes. If an affected airplane is imported and placed on the U.S. Register in the future, the FAA provides the following cost estimates to comply with this AD:

<b>Estimated Costs for Required Actions</b>		
<b>Labor cost</b>	<b>Parts cost</b>	<b>Cost per product</b>
1 work-hour × \$85 per hour = \$85 per RDU	\$0	\$85 per RDU

The FAA has received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

## **List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):



**2020-22-08 Airbus SAS:** Amendment 39-21304; Docket No. FAA-2020-0968; Project Identifier MCAI-2020-00974-T.

**(a) Effective Date**

This AD becomes effective November 19, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Airbus SAS airplanes identified in paragraphs (c)(1) through (6) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020-0155, dated July 14, 2020 ("EASA AD 2020-0155").

- (1) Model A320-251N and -271N airplanes.
- (2) Model A321-251N, -271N, -272N, -252NX, and -271NX airplanes.
- (3) Model A330-243 airplanes.
- (4) Model A330-343 airplanes.
- (5) Model A330-941 airplanes.
- (6) Model A350-941 and -1041 airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 23, Communications; 44, Cabin systems.

**(e) Reason**

This AD was prompted by reports of removable display units (RDUs) found undocked from the hosting display docking stations (DDS). The FAA is issuing this AD to address undocked RDUs, which could lead to detachment of an RDU, possibly resulting in injury to airplane occupants.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020-0155.

## **(h) Exceptions to EASA AD 2020-0155**

(1) Where EASA AD 2020-0155 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2020-0155 does not apply to this AD.

(3) Where the EASA AD specifies “any discrepancies,” those discrepancies include damage or deformity to the DDS tab, a jammed butterfly latch, a RDU that does not engage easily, and a RDU that does not latch.

(4) Where paragraph (3) of the EASA AD specifies a compliance time of “before next flight,” that compliance time does not apply to this AD.

(5) Where AOT A44P001-20-00 and A23L001-20-00, as specified in EASA AD 2020-0155, specify the gap must be equal to or greater than 4.2mm, for this AD, the gap must be greater than 4.0mm.

## **(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2020-0155 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

## **(j) Related Information**

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3225; email: dan.rodina@faa.gov.

## **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0155, dated July 14, 2020.

(ii) [Reserved]

(3) For information about EASA AD 2020-0155, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; Internet: [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0968.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 16, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-24345 Filed 11-3-20; 8:45 am]